

SDMS DocID

557616

**Site Name:** Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA

Photo: 1-1

Time: 0935

**CERCLIS No.:** MAD046128559

**TDD No.:** 95-07-0065

Photographer: M. Jennings

**Date:** 2 May 1996

**Description:** LD = Northwest; Monitoring Well MC-14 foreground

fire station in background.



Site Name: Covitch Property / Former ATF Davidson Co.

Legation: Northbridge MA Photo: 1-2

Location: Northbridge, MA CERCLIS No.: MAD046128559

TDD No.: 95-07-0065

Photographer: M. Jennings

**Date:** 2 May 1996 **Time:** 0940

. **Description:** LD = Northwest; Monitoring Well MC-13, inoperable

due to snow plow damage.



70

'Site Name: Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA Photo: 1-3

**CERCLIS No.:** MAD046128559

**TDD No.:** 95-07-0065

Photographer: M. Jennings

**Date:** 2 May 1996 **Time:** 0941

**Description:** LD = Southwest; 250-gallon diesel fuel aboveground

storage tank.



£.

Photo: 1-4

1.3

**Site Name:** Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA CERCLIS No.: MAD046128559

**TDD No.:** 95-07-0065

Photographer: M. Jennings

**Description:** LD = Northwest; cover for former underground storage tank area along north side of Building No. 12.



집

Site Name: Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA Photo: 1-5

**CERCLIS No.:** MAD046128559

TDD No.: 95-07-0065 Photographer: M. Jennings

**Date:** 2 May 1996 Time: 0945

**Description:** LD = West; view from Covitch Property towards Arcade property showing rolloff, abandoned equipment, debris pile

and stained soil; Arcade building in background.



Location: Northbridge, MA Photo: 1-6

CERCLIS No.: MAD046128559 TDD No.: 95-07-0065

Photographer: M. Jennings

**Date:** 2 May 1996 Time: 0950

**Description:** LD = South; Monitoring Well MC-15, Mumford River

in background.



Location: Northbridge, MA Photo: 1-7

**CERCLIS No.:** MAD046128559

TDD No.: 95-07-0065

Photographer: M. Jennings

**Description:** LD = Southwest; view from Covitch Property of a sign

indicating that fishing occurs along Mumford River.



7

Site Name: Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA Photo: 1-8

CERCLIS No.: MAD046128559 TDD No.: 95-07-0065

Photographer: M. Jennings

**Description:** LD = Northwest; debris pile and area of stained soil on the Covitch Property, west of Building 12, fence dividing Covitch and Arcade property in background.



Location: Northbridge, MA Photo: 1-9

**CERCLIS No.:** MAD046128559

**TDD No.:** 95-07-0065

Photographer: M. Jennings

Date: 2 May 1996 Time: 0954

**Description:** LD = West; debris pile, stained coal ash-like material

10

area and dismantled storage tank west of Building No. 12.



Site Name: Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA Photo: 1-10

Location: Northbridge, MA
CERCLIS No.: MAD046128559

TDD No.: 95-07-0065

Photographer: M. Jennings

**Date:** 2 May 1996 **Time:** 0956

**Description:** LD = North; dismantled 2 horsepower/3 phase electric

mower on the Covitch property west of Building No. 12.



Photo: 1-11

Site Name: Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA **CERCLIS No.:** MAD046128559

**TDD No.:** 95-07-0065

Photographer: M. Jennings

Date: 2 May 1996 Time: 0957

**Description:** LD = Northwest; typical appearance of the "coal ashfoundry sand fill material" on the Covitch property west of Building No. 12.



Site Name: Covitch Property / Former ATF Davidson Co. **Photo: 1-12** Location: Northbridge, MA

**CERCLIS No.:** MAD046128559

**TDD No.:** 95-07-0065

Photographer: M. Jennings

**Date:** 2 May 1996

Time: 1000 **Description:** LD = Southeast; inoperable, Monitoring Well MC-12,

located along the west of Building No. 12.



Site Name: Covitch Property / Former ATF Davidson Co. Location: Northbridge, MA **Photo:** 1-13

**CERCLIS No.:** MAD046128559

**TDD No.:** 95-07-0065

Photographer: M. Jennings

Date: 2 May 1996 **Time:** 1005

**Description:** LD = Southeast; inoperable Monitoring Well MC-11 (concrete seal and well casings), and a plastic discharge pipe to the

Mumford River.



Location: Northbridge, MA Photo: 1-14

**CERCLIS No.:** MAD046128559

TDD No.: 95-07-0065

Photographer: M. Jennings

**Description:** LD = South; unknown concrete discharge pipe to the

Mumford River, south of Covitch Building No. 12.



Site Name: Covitch Property / Former ATF Davidson Co. Location: Northbridge, MA Photo: 1-15

**CERCLIS No.:** MAD046128559

**TDD No.:** 95-07-0065

Photographer: M. Jennings

Date: 2 May 1996 Time: 1014 **Description:** LD = South; Monitoring Well MC-10, note minor

snowplow damage to well cement casing, north side of Covitch

Building No. 23 in background.



Site Name: Covitch Property / Former ATF Davidson Co. Photo: 1-16 Location: Northbridge, MA

**CERCLIS No.:** MAD046128559

TDD No.: 95-07-0065

Photographer: M. Jennings

**Date:** 2 May 1996

Time: 1015

**Description:** LD = Northeast; view of parking area within courtyard, looking at Covitch Buildings No. 9, 10, and 11 in background.



Time: 1016

Site Name: Covitch Property / Former ATF Davidson Co.
Location: Northbridge, MA Photo: 1-17

Location: Northbridge, MA CERCLIS No.: MAD046128559

**TDD No.:** 95-07-0065

Photographer: M. Jennings

Date: 2 May 1996

**Description:** LD = Northwest; view of former storage tank area (with ponded storm water), along south side of Covitch Building No.

11.



7

Site Name: Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA Photo: 1-18

**CERCLIS No.:** MAD046128559 **TDD No.:** 95-07-0065

Photographer: M. Jennings

Date: 2 May 1996 Time: 1020

**Description:** LD = North; former electrical transformer area with connections visible along east side of Covitch Building No. 12.



Time: 1022

Site Name: Covitch Property / Former ATF Davidson Co. Location: Northbridge, MA Photo: 1-19

CERCLIS No.: MAD046128559

TDD No.: 95-07-0065

Photographer: M. Jennings

**Date: 2 May 1996** 

**Description:** LD = North; former air stripping column for the inactive pump and treat groundwater remediation system. Located

along south side of Covitch Building No. 9.



N

Site Name: Covitch Property / Former ATF Davidson Co.
Location: Northbridge, MA Photo: 1-20

Location: Northbridge, MA CERCLIS No.: MAD046128559

TDD No.: 95-07-0065

Photographer: M. Jennings

**Date:** 2 May 1996 **Time:** 1022

**Description:** LD = Northeast; former air stripping column mounted

to Covitch Building No. 9.



Site Name: Covitch Property / Former ATF Davidson Co.
Legation: Northbridge MA Photo: 1-21

Location: Northbridge, MA CERCLIS No.: MAD046128559

**TDD No.:** 95-07-0065

Photographer: M. Jennings

**Date:** 2 May 1996 Time: 1022

**Description:** LD = Northeast; close-up view of air stripping column mounted to Covitch Building No. 9.



10

Site Name: Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA Photo: 1-22

**CERCLIS No.:** MAD046128559

**TDD No.:** 95-07-0065

Photographer: M. Jennings

**Date:** 2 May 1996 Time: 1024

**Description:** LD = Southeast; observation well for pump and treat

system in raceway area; Covitch Building No. 9 to the left.

Transformer in background.



Site Name: Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA **Photo:** 1-23

CERCLIS No.: MAD046128559

**TDD No.:** 95-07-0065

Photographer: M. Jennings

**Date:** 2 May 1996

Time: 1025

**Description:** LD = Northwest; observation well for pump and treat system, in raceway area; Covitch Building No. 9 to the right of the

transformer in background.



꼰

Site Name: Covitch Property / Former ATF Davidson Co. Location: Northbridge, MA Photo: 1-24 CERCLIS No.: MAD046128559 TDD No.: 95-07-0065

Photographer: M. Jennings

Date: 2 May 1996 Time: 1030
Description: LD = Northeast; lock mechanism for Raceway

headwater diversion channel between Covitch Building No. 19 and

10.



1.

Site Name: Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA Photo: 1-25

**CERCLIS No.:** MAD046128559

**TDD No.:** 95-07-0065

Photographer: M. Jennings

**Date:** 2 May 1996 **Time:** 1031

**Description:** LD = Northeast; lock mechanism for Raceway headwater diversion channel between Covitch Building No. 19 and

16.



7.

N

Site Name: Covitch Property / Former ATF Davidson Co. Location: Northbridge, MA Photo: 1-26

**CERCLIS No.:** MAD046128559

**TDD No.:** 95-07-0065

Photographer: M. Jennings

**Date:** 2 May 1996 **Time:** 1040

**Description:** LD = West; crushed drum below iron walkway,

adjacent to (east) Building No. 19.



77

Site Name: Covitch Property / Former ATF Davidson Co.
Location: Northbridge, MA Photo: 1-27

Location: Northbridge, MA
CERCLIS No.: MAD046128559

TDD No.: 95-07-0065

Photographer: M. Jennings

**Date:** 2 May 1996 Time: 1042 **Description:** LD = West; three non-PCB labeled (blue label)

transformers located below iron walkway on west side of Building

No. 19; viewed through chain line fence.



20

Site Name: Covitch Property / Former ATF Davidson Co.
Location: Northbridge, MA Photo: 1-28

CERCLIS No.: MAD046128559

**TDD No.:** 95-07-0065

Photographer: M. Jennings

Date: 2 May 1996

Description: LD = East; remnants of Monitoring Well MC-7

(inoperable); open 55-gal trash drum in background.

